

EUC\MGB2\MGB2\_L1,2\_MLI\_Y.ema


Variante A

Allpolig

V1.0

==Safety=Safety\_systems++MGB2\_AR+L1\_2&amp;MLI#Y-2150206/2

-A4

**EUCHNER MGB2**156392  
MGB2-L2-MLI-U-Y0000-BJ  
AUSWERTEMODUL ZUHALTUNG ELEKTR.X1:MLI  
universal plug

EUC\MGB2\MGB2\_L1,2\_MLI\_Y.ema


Variante B

Allpolig

V1.0

==Safety=Safety\_systems++MGB2\_AR+L1\_2&amp;MLI#Y-2150206/2

-A5

**EUCHNER MGB2**156392  
MGB2-L2-MLI-U-Y0000-BJ  
AUSWERTEMODUL ZUHALTUNG ELEKTR.X2:MLI  
direct  
plugX1:MLI  
universal plug

EUC\MGB2\MGB2\_L1,2\_MLI\_Y.ema


Variante C

Allpolig

V1.0

==Safety=Safety\_systems++MGB2\_AR+L1\_2&amp;MLI#Y-2150206/2

-A6

**EUCHNER MGB2**156392  
MGB2-L2-MLI-U-Y0000-BJ  
AUSWERTEMODUL ZUHALTUNG ELEKTR.X2:MLI  
cable  
connectX1:MLI  
universal plug

			Datum	15.11.18	<b>EUCHNER</b>	Blatt name: <b>156392</b>		
			Bearb.	AJ				
			Gepr.					
Änderung	Datum	Name	Urspr.		Ersatz von	Ersetzt durch		